Quarterly Recordable Environmental Incident Report

Mereenie Oil and Gas Field - Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum* (*Environment*) Regulations 2016 for the period 1 October to 31 December 2023.

Nil Incident Report □							
Interest Holder Name	 Central Petroleum Mereenie Pty Ltd Macquarie Mereenie Pty Ltd NZOG Mereenie Pty Ltd Cue Mereenie Pty Ltd 	Title holder business address	 369 Ann Street Brisbane Qld 4000 50 Martin Place Sydney NSW 2000 Sydney NSW 2000 Melbourne VIC 3000 	EMP title for the activity	Mereenie Oil and Gas Field Environment Management Plan		
Activity type	Production	Quarter, Year	Quarter 4, 2023	Title details	Operating Licence 4 and 5		

SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION								
Incident date and time	All material facts and circumstances	Environmental outcome(s) and/or performance standard(s) breached or environmental impact or risk not specified in approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent similar incident occurring in future				
14 October 2023 08:37	During routine plant checks an Operator noticed a wet patch of ground. An investigation found a minor drip from a pin-sized hole in the closed produced water drainpipe. The total spill volume was approximately 100ml.	No uncontrolled or unregulated releases.	A temporary clamp was fitted to stop the drip.	 The impacted soil was removed. Regular maintenance and routine inspection of area assessed as appropriate. 				
11 December 2023 13:21	While depressurising a pig receiver, the drain line leaked oily water to grade at the Central Treatment Plant. The total spill volume was approximately 20 litres.	No uncontrolled or unregulated release of wastes.	The unit was isolated and tagged out to avoid further spillage through the compromised drain line.	 The impacted soil was removed. The compromised drain line was replaced. 				