

# Quarterly Recordable Environmental Incident Report



## Northern Territory Drilling Campaign – Environmental Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum (Environment) Regulations 2016* for the period 01 April to 30 June 2022.

Nil Incident Report <input type="checkbox"/>					
<b>Interest Holder Name:</b>	Central Petroleum Ltd	<b>Title holder business address</b>	Level 7, 369 Ann Street Brisbane Qld 4000	<b>Title of environmental management plan for the activity:</b>	Northern Territory Drilling Campaign - Environmental Management Plan
<b>Activity type:</b>	Drilling	<b>Quarter, Year</b>	Quarter 2, 2022	<b>Title details:</b>	Operating Licence 3 and 4, Production Licence 6 and 7, and Exploration Permit 82

### SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION 2016

Incident date and time	All material facts and circumstances	Environmental outcome(s) and/or performance standard(s) breached or environmental impact or risk not specified in Approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent similar incident occurring in future
06 June 2022	During drilling activities approximately 6bbls (954L) of potable water with 2% cement additive was released during the mixing process. The release was caused by a blockage in the exhaust port air actuation process which resulted in the valve being stuck in an open position. The release to grade was contained within the lease area.	<ul style="list-style-type: none"> <li>No releases of contaminants resulting in long-term contamination of the soil.</li> <li>Ministerial Condition 2: In the event of any accidental release of contaminated that exceeds 200L, the interest holder must provide a written report to DPEWS within 24 hours of the incident being detected.</li> </ul>	<ul style="list-style-type: none"> <li>Mixing was stopped immediately.</li> <li>Additive containing water was removed via vacuum truck and deposited in sump.</li> </ul>	<ul style="list-style-type: none"> <li>Investigation conducted and found root cause of equipment failure.</li> <li>All valve banks were checked for similar issue prior to future use.</li> </ul>