Recordable Incidents Report: Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010). This report covers the period **9 September 2020 to 8 December 2020.**

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS							
QUARTERLY REPORTING FOR PERIOD 9/09/2020 TO 8/12/2020							
ENVIRONMENT MANAGEMENT PLAN – Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South (E2018/0024-0010)							
Incident Date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment)	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil