## **Quarterly Recordable Environmental Incident Report**



## Mereenie Oil and Gas Field - Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum (Environment) Regulations 2016* for the period 1 July to 30 September 2022.

Nil Incident Report □							
Interest Holder Name	<ul> <li>Central Petroleum Mereenie Pty Ltd</li> <li>Macquarie Mereenie Pty Ltd</li> <li>NZOG Mereenie Pty Ltd</li> <li>Cue Mereenie Pty Ltd</li> </ul>	Title holder business address	<ul> <li>369 Ann Street Brisbane Qld 4000</li> <li>50 Martin Place Sydney NSW 2000</li> <li>Sydney NSW 2000</li> <li>Melbourne VIC 3000</li> </ul>	EMP title for the activity	Mereenie Oil and Gas Field Environment Management Plan		
Activity type	Production	Quarter, Year	Quarter 3, 2022	Title details	Operating Licence 4 and 5		

SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION								
Incident date and time	All material facts and circumstances	Environmental outcome(s) and/or performance standard(s) breached or environmental impact or risk not specified in approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent similar incident occurring in future				
11 July 2022 09:00	An operator during daily checks noticed that there was icing around control valve on the Plant 1 Refrigeration Unit. Upon inspection liquid propane was observed coming out of the stem packing Seal. A Site wide notification was sent out via radio to make everyone aware of the leak. The valves next to the control valve were closed and also next set of boundary Isolation's. While propane boiled off the leak was monitored from a distance next to the Compressor K-403 in case a Plant ESD had to be activated. Valves have sealed leak and stopped any immediate hazard in the area.	No uncontrolled gas release.	<ul> <li>Area was made safe.</li> <li>Valves and isolations put in place and locks installed.</li> </ul>	<ul> <li>Removed and repaired the control valve.</li> <li>Area is regularly inspected so no changes to inspection schedule required.</li> </ul>				