Recordable Incidents Report: Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010). This report covers the period **10 June 2020 to 8 September 2020**.

| SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS | | | | | | | |
|--|--------------------|------------------|--|--------------------|--|---|------------------------------------|
| QUARTERLY REPORTING FOR PERIOD 10/06/2020 TO 8/09/2020 | | | | | | | |
| ENVIRONMENT MANAGEMENT PLAN – Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South (E2018/0024-0010) | | | | | | | |
| Incident Date (dd/mm/yy) | Area / Location | Incident Summary | Actual Consequence (From Risk Assessment) | Corrective Actions | Relevant Environment Performance Standard | Effect on Relevant Environmental Outcome | Other Regulator Notification |
| Nil | Nil | Nil | Nil | Nil | Nil | Nil | Nil |