

# Quarterly Recordable Environmental Incident Report

## Palm Valley Gas Field – Environment Management Plan

The following information has been compiled on behalf of interest holders to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations 2016 for the period 1 April to 30 June 2023.

<b>Nil Incident Report</b> <input type="checkbox"/>					
<b>Interest Holder Name:</b>	<ul style="list-style-type: none"> <li>▪ Central Petroleum (NT) Ltd</li> <li>▪ NZOG Palm Valley Pty Ltd</li> <li>▪ Cue Palm Valley Pty Ltd</li> </ul>	<b>Title holder business address</b>	<ul style="list-style-type: none"> <li>▪ 369 Ann Street Brisbane Qld 4000</li> <li>▪ Sydney NSW 2000</li> <li>▪ Melbourne VIC 3000</li> </ul>	<b>Title of environmental management plan for the activity:</b>	Palm Valley Gas Field – Field Environmental Management Plan
<b>Activity type:</b>	Production	<b>Quarter, Year</b>	Quarter 2, 2023	<b>Title details:</b>	Operating Licence 3

### SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION 2016

Incident date and time	All material facts and circumstances	Environmental outcome(s) and/or performance standard(s) breached or environmental impact or risk not specified in Approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent similar incident occurring in future
26 April 2023 14:21	The level float in the washdown pad sump failed to activate the automated pump resulting in approximately 100ltrs of oily water to spill to grade. The spill was contained to the previously disturbed operational area adjacent to the pad. There was not impact to the surrounding environment.	<ul style="list-style-type: none"> <li>▪ No uncontrolled releases</li> </ul>	<ul style="list-style-type: none"> <li>▪ Spill contained within existing pre-existing disturbed operational area.</li> <li>▪ Float has been repaired.</li> <li>▪ Contaminated soil removed and replaced with fresh soil.</li> </ul>	<ul style="list-style-type: none"> <li>▪ Investigate options to improve wash pad areas.</li> </ul>
24 June 2023 22:30	An Operator during a routine inspection identified approximately 10ltrs of oily water spill to grade a near compressors 4 and 5 from the open drain system.	<ul style="list-style-type: none"> <li>▪ No uncontrolled releases</li> </ul>	<ul style="list-style-type: none"> <li>▪ Spill contained within existing pre-existing disturbed operational area.</li> <li>▪ Contaminated soil removed and replaced with fresh soil.</li> </ul>	<ul style="list-style-type: none"> <li>▪ Investigate implementing workorder for regular drain cleaning.</li> </ul>