Recordable Incidents Report: McArthur Basin 2019 Drilling Program - Environmental Management Plan (EMP) (Ref: NTEPA20190033-003~0007)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the McArthur Basin 2019 Drilling Program - Environmental Management Plan (EMP) (Ref: NTEPA20190033-003~0007). This is for the reporting period from the **19 July 2019 to 17 October 2019.**

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 12/06/2019 TO 10/09/2019							
ENVIRONMENT MANAGEMENT PLAN – Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South (E2018/0024-0010)							
Incident Date (dd/mm/yy)	**Area / Location**	**Incident Summary**	**Actual Consequence (From Risk Assessment)[1]**	**Corrective Actions**	**Relevant Environment Performance Standard**	**Effect on Relevant Environmental Outcome**	**Other Regulator Notification**
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil