## Recordable Incidents Summary Report: Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034, Santos Ref: MAB-PLN-005, Revision 1). This is the second reporting period post approval of the EMP, and covers the period **26 May 2019 to 24 August 2019.**

| **SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 26/05/2019 TO 24/08/2019** | | | | | | | |
|---|---|---|---|---|---|---|---|
| **ENVIRONMENT MANAGEMENT PLAN – Tanumbirini North Water Bore Monitoring Program (E2018/0019-0034)** | | | | | | | |
| **Incident Date (dd/mm/yy)** | **Area / Location** | **Incident Summary** | **Actual Consequence (From Risk Assessment)[1]** | **Corrective Actions** | **Relevant Environment Performance Standard** | **Effect on Relevant Environmental Outcome** | **Other Regulator Notification** |
| Nil | Nil | Nil | Nil | Nil | Nil | Nil | Nil |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |