Recordable Incidents Summary Report: Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034, Santos Ref: MAB-PLN-005, Revision 1). This reporting period covers **23 August 2020 to 21 November 2020.**

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 23/08/2020 TO 21/11/2020							
ENVIRONMENT MANAGEMENT PLAN – Tanumbirini North Water Bore Monitoring Program (E2018/0019-0034)							
Incident Date (dd/mm/yy)	**Area / Location**	**Incident Summary**	**Actual Consequence (From Risk Assessment)[1]**	**Corrective Actions**	**Relevant Environment Performance Standard**	**Effect on Relevant Environmental Outcome**	**Other Regulator Notification**
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil