

## Recordable Incidents Summary Report: Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Tanumbirini North Water Bore Monitoring Program Environmental Management Plan (EMP) (Ref: E2018/0019-0034, Santos Ref: MAB-PLN-005). This reporting period covers **1 July 2021 to 30 September 2021**.

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 1/07/2021 TO 30/09/2021							
ENVIRONMENT MANAGEMENT PLAN – Tanumbirini North Water Bore Monitoring Program (E2018/0019-0034)							
Incident Date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment) <sup>1</sup>	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil