

[REDACTED]
Sent: Sunday, 17 September 2023 4:19 PM

[REDACTED]
[REDACTED]
Subject: Imperial - written notification _ Carpentaria 1

Importance: High

Good afternoon,

Please accept this e-mail as the follow-up written notification of the initial verbal courtesy call placed at 5pm on 16 Sept @ 1800 413 889.

Contact details of the interest holder

- This written notification is being made on behalf of:
 - Imperial Oil and Gas Pty Ltd.
 - Alex Underwood
 - [REDACTED]

Material facts and circumstances

- A leak was detected between the liners at an above ground treatment tank at the Carpentaria 1 gas well pad location (70 km West of Heart Break Hotel on the Carpentaria Hwy) in EP 187.
- Details:
 - o A potential leak was detected on the morning of 16 Sept
 - o The on-site civils supervisor attended site to investigate, and fluid was identified between liners
 - o The interest holder was made aware that the detected leak was potentially reportable at ~4pm on the 16 Sept
 - o Verbal notification was made to the Onshore gas non-compliance line at ~5pm on the 16 Sept
- There are no notable events leading up to the detection of the leak
- There has been no loss of containment identified outside of the tank

Actions taken to avoid or mitigate material environmental harm

- Evaporation of fluids has been temporarily suspended
- A pump has been set up to remove fluid between the liners
- The integrity of the banded tank pad, the tank is located on, has been verified

Corrective action proposed to be taken to avoid reoccurrence

- Temporarily cease evaporation in the Carpentaria 1 tank and the second above ground treatment tank at Carpentaria 2 until investigation complete
- Create an action plan for fluids contained in the Carpentaria 1 tank

Please let me know if you have any questions on the above.

Regards,

[REDACTED]
InGauge Energy Pty Ltd
[REDACTED]