

Quarterly Recordable Incident Report

Please check the following box if applicable to this report			Nil incident report □		
Interest holder	Tamboran B2 Pty Ltd	Titleholder business	Tamboran Resources Limited	Title of environment	Beetaloo Basin Velkerri,
name:	ABN 42 105 431 525	address:	110-112 The Corso	management plan for	2019-2024 Drilling,
			Manly NSW 2095	the activity:	Hydraulic Fracturing and
					Well Testing
					NT-2050-15-MP-032
					ORI5-4
Activity type:	Drilling, stimulation and well	Quarter and Year:	Q4 2023: 01 October 2023 –	Title details:	EP 76
	testing		31 December 2023	(e.g. EP #, production licences #)	

Incident date and time	All material facts and circumstances (refer to the example in section 4.2.2 of the Incident Reporting Guideline)	Environmental outcome(s) and/or performance standard(s) breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Correct action taken, or proposed, to prevent a similar incident occurring in future
10/10/2023 09:40	Tamboran site inspections were being completed by a local contractor, but sufficient evidence was not retained. A change had occurred from the previous service provider to a new contractor. The new contractor would send verbal updates on the site and photographs. The site is in good standing, however the level of	Records of site inspections had not been retained.	N/A- no risk or impact from incident.	Tamboran has re-implemented the site inspection checklist with the contractor completing the inspections.



Incident date and time	All material facts and circumstances (refer to the example in section 4.2.2 of the Incident Reporting Guideline)	Environmental outcome(s) and/or performance standard(s) breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Correct action taken, or proposed, to prevent a similar incident occurring in future
	information retained is insufficient to demonstrate compliance with the relevant performance standards.			