

Quarterly Recordable Environmental Incident Report



Palm Valley Gas Field – Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum (Environment) Regulations 2016* for the period 1 April and 30 June 2022.

Nil Incident Report <input type="checkbox"/>					
Interest Holder Name:	Central Petroleum (NT) Pty Ltd	Title holder business address	Level 7, 369 Ann Street Brisbane Qld 4000	Title of environmental management plan for the activity:	Palm Valley Gas Field – Field Environmental Management Plan
Activity type:	Production	Quarter, Year	Quarter 2, 2022	Title details:	Operating Licence 3

SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION 2016

Incident date and time	All material facts and circumstances	Environmental outcome(s) and/or performance standard(s) breached or environmental impact or risk not specified in Approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent similar incident occurring in future
04 June 2022 13:45	Venting of gas to formation water tank at Palm Valley 6 identified during daily inspection. Level controller had internal build-up of salt preventing closure and causing vent to be partially blocked in open position and gas to weep into formation water tank. Minor volume of gas could not be calculated.	<ul style="list-style-type: none"> No uncontrolled releases 	<ul style="list-style-type: none"> Clean level control and instrument supply lines and check filters. 	<ul style="list-style-type: none"> Continuation of regular asset inspection program. Additional inspection of level controllers at active well locations.