## Recordable Incidents Report: McArthur Basin 2019 Drilling Program - Environmental Management Plan (EMP) (Ref: NTEPA20190033-003~0007)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the McArthur Basin 2019 Drilling Program - Environmental Management Plan (EMP) (Ref: NTEPA20190033-003~0007). This is for the reporting period from the **17 January 2020 to 16 April 2020**.

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS							
QUARTERLY REPORTING FOR PERIOD 17/01/2020 TO 16/04/2020							
ENVIRONMENT MANAGEMENT PLAN – Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South (E2018/0024-0010)							
Incident Date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment) <sup>1</sup>	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil