

Mereenie Field Workover and Wellhead, Equipment, Safety System and Gathering Line Activities – Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations. During the period from 5 January to 31 March 2021¹.

There were no recordable incidents related to the regulated activities undertaken under the Mereenie Workovers EMP during the reporting period.

SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT)							
QUARTERLY REPORTING FOR PERIOD 5/1/2021 TO 31/3/2021				ENVIRONMENT MANAGEMENT PLAN – Mereenie Field Workover and Wellhead, Equipment, Safety System and Gathering Line Activities			
Incident date	Area / location	Incident summary	Actual consequence (from risk assessment)	Corrective actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Additional Regulator Notification
Nil							

¹ The period of the report is less than the required 90 days however the dates have been amended to reflect the requirement to now report quarterly as per guidance from the Minister on 24 March 2021.