Santos

Recordable Incidents Report: McArthur Basin 2019 Hydraulic Fracturing Program -Environmental Management Plan (EMP) (STO 3-4) (Ref: NTEPA2019/0102-007~0011)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the McArthur Basin 2019 Hydraulic Fracturing Program - Environmental Management Plan (EMP) (Ref: NTEPA2019/0102-007~0011). This is for the reporting period from the **1 April 2022 to 30 June 2022**.

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS	
QUARTERLY REPORTING FOR PERIOD 1/04/2022 TO 30/06/2022	

ENVIRONMENT MANAGEMENT PLAN – McArthur Basin 2019 Hydraulic Fracturing Program – (Ref: NTEPA2019/0102-007~0011)

Incident Date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment)	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification
Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil