# **Quarterly Recordable Incident Report**

This report is required to be submitted under regulation 35(1) of the Petroleum (Environment) Regulations 2016 (the Regulations) and may be published in accordance with regulation 35A(1)(c) of the Regulations. Send the completed form to <u>Onshoregas.DEPWS@nt.gov.au</u> as soon as practicable and in any case no later than 15 days after the end of the reporting period, as referred to in the <u>Onshore Petroleum Incident Reporting Guideline</u>, or as otherwise agreed in writing with the Minister for Environment, Climate Change and Water Security.

#### Section 1 – Interest Holder Details

For petroleum titles held by multiple interest holders, details must be completed for each interest holder. If insufficient room, please attach information to the form.

	Interest Holder 1	Interest Holder 2	Interest Holder 3	Interest Holder 4
Company Name	Imperial Oil & Gas Pty Ltd			
Nominated interest holder for all matters related to Report? If 'no' each interest holder must sign Declaration and will receive related documents unless designated operator authorised to sign and receive documents	⊠ Yes □ No	□ Yes □ No	□ Yes □ No	□ Yes □ No
Authorisation given to an Operator to submit Report and sign Declaration?	⊠ Yes □ No	□ Yes □ No	□ Yes □ No	□ Yes □ No

Section 2 – Recordable Incident Report Details							
EMP title (petroleum title/s)	2021 Carpentaria 1 Work Program EP187	Unique EMP ID	IMP3-4	Date Submitted	April 2024	Nil report?	□ Yes ⊠ No
Activity type	Hydraulic fracturing and extended production testing of the existing C1 vertical exploration well on EP187	Reporting Period <sup>1</sup>	Quarter:	Q1	Year:	2024	

Note 1: Refer to Table 1 of the Onshore Petroleum Incident Reporting Guideline for reporting periods and due dates.



## Section 3 – Recordable Incident Details

Complete this section for each recordable incident within the reporting period, by copying the rows below and completing for each individual recordable incident.							
Incident number							
Incident date	19/03/2024	Incident time	Overnight pm	Date and time interest holder became aware	Morning of 20/03/2024		
Reg 35(3)(c)(ii): All material facts and circumstances refer to Section 5.4.2 of the <u>Onshore Petroleum</u> <u>Incident Reporting Guideline</u>	A minimum of 1100mm freeboard was not achieved between 19/03/2024 and 03/04/24 at the Carpentaria 1 cutting pit due to rainfall associated tropical low ex-cyclone Meagan. Freeboard of 1100mm regained due to fluid evaporation. Actual freeboard levels have been reported to DEPWS each week in the weekly report submissions. Freeboard levels and dates provided in Section 5.				Supporting information attached ⊠ Yes □ No		
Did the incident result in an environmental impact or risk not specified in approved EMP?	□ Yes ⊠ No	If yes, describe th extent of the env impact or risk			Supporting information attached □ Yes ⊠ No		
Did the incident result in a contravention of a performance standard(s) specified in the approved EMP?	⊠ Yes □ No	If yes, describe the contravention of the environmental performance standard(s)Performance standard: "Freeboard for all wastewater sumps, flowback water tanks and produced water tanks maintained at all times" was not achieved between 19/03/2024 and 03/04/24.			Supporting information attached ⊠ Yes □ No		
Is the incident inconsistent with an environmental outcome(s) specified in the approved EMP?	□ Yes ⊠ No	If yes, describe h incident is incons the environment	sistent with		Supporting information attached □ Yes ⊠ No		
If the answer to the above questions is 'No', consider whether the incident is a recordable incident.							
Reg 35(3)(c)(iii): Action taken to avoid or mitigate any environmental impacts or risks of the incident refer to Section 5.4.3 of the <u>Onshore Petroleum</u> <u>Incident Reporting Guideline</u>	Monitoring undertaken via cameras, remote sensors, helicopter deployment and weather forecasts to verify remaining freeboard adequate to avoid overtopping. No environmental impact occurred. Photograph attached showing contingency freeboard availability.				Supporting information attached ⊠ Yes □ No		

Reg 35(3)(c)(ii): Corrective action	Work with DEPWS to obtain approval to close the Carpentaria 1 cuttings prior to the onset of the next	Supporting information
taken, or proposed, to prevent a	wet season.	attached
similar incident occurring in future		🗆 Yes 🖂 No
refer to Section 5.4.4 of the Onshore Petroleum		
Incident Reporting Guideline		

#### Section 4 - Declaration

A person with legal authority to sign on behalf of the interest holder, or all interest holders (if more than one), must sign the declaration.

I hereby declare that I:

- am authorised to make this declaration.
- confirm that, to the best of my knowledge all information provided addresses the relevant matters and is true, correct, complete, and does not contain misleading information
- am aware that it is an offence under section 107 of the *Petroleum Act* 1984 to give an authorised person information that I know, or ought to reasonably know, to be false or misleading in a material manner particular
- understand that all information supplied as part of this form, including attachments, may be disclosed publically in accordance with regulation 35A of the Petroleum (Environment) Regulations 2016, and consistent with the requirements of the Information Privacy Principles (IPPs) in the *Information Act* 2002.

If report being signed by interest holder/s (include attachment if more room is required to complete the below table)							
	Interest Holder 1	Interest Holder 2	Interest Holder 3	Interest Holder 4			
Company Name	Imperial Oil & Gas Pty Ltd						
Signature							
Name (print)	Robin Polson						
Position	Chief Financial Officer						
Date	12 April 2024						
Email	compliance@empiregp.net						

Department of **Environment**, **Parks and Water Security** 21 December 2023 | Version 2.0 Page 3 of 5


### Section 5 – Supporting Information

Figure 1: Freeboard availability of Carpentaria 1 Cutti						
	Date	Freeboard Availability (mm)				
	18/3/24	1205				
	19/3/24	1029				
	20/3/24	988				
	21/3/24	920				
	22/3/24	925				
	23/3/24	935				
	24/3/24	957				
	25/3/24	975				
	26/3/24	995				
	27/3/24	1012				
	28/3/24	1025				
	29/3/24	1044				
	30/3/24	1036				
	31/3/24	1036				
	1/4/24	1050				
	2/4/24	1067				
	3/4/24	1083				
	4/4/24	1106				

ting Pit. Fi

Department of Environment, Parks and Water Security 21 December 2023 | Version 2.0 Page 4 of 5

#### Quarterly Recordable Incident Report



**Caption:** Photograph taken 21/3/24 showing freeboard availability of Carpentaria 1 cuttings pit. Still ample space to contain multiple significant rainfall events and not at risk of overtopping.

Department of **Environment, Parks and Water Security** 21 December 2023 | Version 2.0 Page 5 of 5