

Quarterly Recordable Incident Report



Please check the following boxes if applicable to this report: Nil Incident Report

Interest holder name:	Imperial Oil and Gas	Titleholder business address:	Level 5, 6-10 O'Connell Street, Sydney, NSW 2000	Title of environment management plan for the activity:	IMP 4-3 2021-2025 Work Program
Activity type:	Seismic, Drilling, & Hydraulic Fracturing	Quarter, Year:	Q3, 1/07/2023 to 30/09/2023	Title details:	EP 187

Incident date and time	All material facts and circumstances	Environmental outcome Or performance standard breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent a similar incident occurring in future
16/7/23	Field Operator noted graffiti on access signs to Carpentaria 1, which is also the access gate to Carpentaria 4.	Table 30 Measurement Criteria: <ul style="list-style-type: none"> Community complaints register shows no complaints received in regards to the use of the land. 	Field Officer cleaned signs 17/7/23	Beetaloo Operational Security Team advised. Reviewing security measures to determine camera capture locations.