

# Quarterly Recordable Environmental Incident Report



## Mereenie Field Workover and Wellhead Equipment, Safety Systems and Gathering Line Activities – Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum (Environment) Regulations 2016* for the period 01 April to 30 June 2022.

| Nil Incident Report <input checked="" type="checkbox"/> |  |                                      |   |   |  |
|---|--|--------------------------------------|---|---|--|
| <b>Interest Holder Name:</b>                            | <ul style="list-style-type: none"> <li>Central Petroleum Mereenie Pty Ltd</li> <li>Macquarie Mereenie Pty Ltd</li> </ul> | <b>Title holder business address</b> | <ul style="list-style-type: none"> <li>Level 7, 369 Ann Street Brisbane Qld 4000</li> <li>Level 6 / 50 Martin Place, Sydney, NSW, 2000</li> </ul> | <b>Title of environmental management plan for the activity:</b> | Mereenie Field Workover and Wellhead Equipment, Safety Systems and Gathering Line Activities |
| <b>Activity type:</b>                                   | Production   | <b>Quarter, Year</b>                 | Quarter 2, 2022   | <b>Title details:</b>   | Operating Licence 4<br>Operating Licence 5   |

| SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION |                                      |  |  |   |
|---|--------------------------------------|--|--|---|
| Incident date and time  | All material facts and circumstances | Environmental outcome(s) and/or performance standard(s) breached<br>OR<br>environmental impact or risk not specified in Approved EMP | Immediate Action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident | Corrective action taken, or proposed, to prevent similar incident occurring in future |
|   |                                      |  |  |   |