

Quarterly Recordable Incident Report

Please check the following box if applicable to this report			Nil incident report ⊠		
Interest holder name:	Tamboran B2 Pty Ltd ABN 42 105 431 525	Titleholder business address:	Tamboran Resources Limited 110-112 The Corso Manly NSW 2095	Title of environment management plan for the activity:	Beetaloo W-1 NT-2050-15-MP-39 (ORI8-2)
Activity type:	Exploration and appraisal activities for the Beetaloo W site	Quarter and Year:	1 January – 31 March 2023 Q1 2023	Title details: (e.g. EP #, production licences #)	117

Incident date and time	All material facts and circumstances (refer to the example in section 4.2.2 of the Incident Reporting Guideline)	Environmental outcome(s) and/or performance standard(s) breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Correct action taken, or proposed, to prevent a similar incident occurring in future
Nil				



INCIDENT							
□ Injury □ Illness ☑ Environmental (see additional detail) □ Community Complaint □ Cultural Heritage □ Land Transport	☐ Property Damage or Loss ☐ Process Safety ☐ Security ☐ Regulatory Non-Compliance ☐ Near Miss ☐ Other (please provide details below) Click or tap here to enter text.	Environmental Spill volume (litres): 20 litres Contaminant: Other (details below) CF150FBS - surfactant Contained on site Yes No					
Consequence Rating – Risk matrix must be used when determining ranking							
Note one box must be checked for both Actual and Potential consequence							
Actual Poter		ial					
□ 1-Minor □ 2-Moderate □ 3-Serior	us ⊠ 1-Mi	inor 🗆 2-Moderate 🗆 3-Serious					
☐ 4-Major ☐ 5-Critical ☐ 6-Catastro	ajor □ 5-Critical □ 6-Catastrophic						